

N49RF AVAPS DropSonde Log

Project: WS 06 Flight ID: 060308N Flt Dir: MARTY

Mission: _____ Flight #: R.F. 22 Status: Sys 1 _____ Sys 2 _____ Launcher S/N: _____

Drop #	Sonde Serial Number	Chn. #	Time (Zulu)	Press. offset	Winds time	Operator Initials	Comments /Status/ Failure Reason	\$	GOOD ☒
1	053 416 076	1	21:31	Ø	1	MER		N	✓
2	053 116 252	1	21:54	Ø	1			N	✓
3	053 416 073	1	22:19	Ø	1		FAST FALL	N	
4	051 926 053	3	22:25	+1.5	1		FAST FALL	N	
5	053 116 012	1	22:44	Ø	1			N	✓
6	051 926 182	1	23:08	+1.4	1			N	✓
7	053 156 024	1	23:31	Ø	1			N	✓
8	053 626 304	1	23:55	+1.7	1			N	✓
9	053 316 097	1	00:18	Ø	1			N	✓
10	053 416 385	1	00:40	+1.4	1		FAST FALL	N	
11	053 416 092	3	00:42	Ø				N	✓
12	053 636 115	1	01:02	+1.5				N	✓
13	051 926 015	1	01:25	1.Ø				N	
14	053 626 309	1	01:49	+1.5					
15									
16									
17									
18									
19									
20									
21									
22									
23									
24									
25									
26									
27									
28									
29									
30									
31									
32									
33									

\$ Codes A = AOC N = NHC/NWS H = HRD OW = NESDIS _____ = _____ = _____