

N49RF AVAPS DropSonde Log

Project: WS 06 Flight ID: 060314N Flt Dir: MARTY

Mission: OZONE Flight #: RF24 Status: Sys 1 ☒ Sys 2 ☒ Launcher S/N: 02

Drop #	Sonde Serial Number	Chn. #	Time (Zulu)	Press. offset	Winds time	Operator Initials	Comments /Status/ Failure Reason	\$	GOOD ☒
1	053636116	1	0036	0.6	2	<i>JOY</i>			☒
2	053416150	1	0100	0	3		FAST FALL		☒
2	053416151	3	0102	0.4	3				☒
3	053626250	1	0124	0.5	4				☒
4	053636124	1	0145	0.4	3				☒
5	053636122	3	0204	0.7	2				☒
6	053626253	1	0223	0.5	2				
8									
9									
10									
11									
12									
13									
14									
15									
16									
17									
18									
19									
20									
21									
22									
23									
24									
25									
26									
27									
28									
29									
30									
31									
32									
33									

\$ Codes A = AOC N = NHC/NWS H = HRD OW = NESDIS _____ = _____ = _____