

U.S. Dep't. of Commerce / OMAO / NOAA / Aircraft Operations Center

FLT ID: 20150702I1 From: KSLN To: KSLN
 FLT #: Blk In: 0739 Z Lnd Time: 0732 Z
 ETD: 0100 Z Blk Out: 0150 Z T/O Time: 0157 Z
 ETE: Total Blk: 5:49 (5.8) Total Flt: 5:35 (5.6)
 Sponsoring Org: OAR/NSSL Program: PELAN Purpose: FLT#4

AOC Flight Crew

Aircraft Commander: KIBBEY SSA: ~~RICHARDS~~ MASCARO
 Co-Pilot: KERNS / KAHN / ABITBOL AVAPS: ~~MASCARO~~
 Navigator: GALLAGHER Scientists: FOERSTER / BLACK
 Flight Eng: KLIPPEL, DARBY Scientists: LYONS / JEWETT
 Flt Director: DAMIANO, HOLMES Scientists:
 SEB: PEEK, LYNCH, Scientists:
 Crew Chief: Visitors: FROELICH, 1

	A/C - Takeoff	Wx Station - Takeoff	A/C - Land	Wx Station - Land
Pressure	963.0	29.80 / 963.2	964.5	29.85 / 965.3

AS REQUIRED BY ORM

	YES	NO	REMARKS
VOLCANIC ASH			
SCIENCE MISSION WITHIN BOUNDARY LAYER			
LACK OF PRECIPITATION			
RELATIVE HUMIDITY AT OR ABOVE 80%			
LARGE AIR-SEA TEMPERATURE GRADIENT			
HIGH SURFACE WINDS			
LONG FETCH AND/OR DURATION OF SFC WIND			
SEA SALT ACCRETION FORECAST			
SEA SALT ACCRETION OBSERVED			

Dropsondes Good: Bad: Sent:
 AXBT Good: Bad: Sent:
List other data sources in Remarks section

Remarks (Storm VDM Identifier, Mission ID, Fix Times)

Storm Number Identifier (VDM): (ie: AL072012)	Fix #	VDM Ob Num	Fix Time / SLP
TCPOD/WSPOD Mission ID: WXWXA PECAND (ie: NOAA2 2418A SANDY)			
Remarks:			

OPS FAX 813-828-4529 IP 40N 95W Bad TDM1
 Nav flight SLN VPrinter not working 1st panel

I-be delay for WX 031321Z LF Failed

PIP is inop shortly after T/O 01066 cur

964.95 Lnd

SLP 1007.3

SLP 1009.3