

**MISS PIGGY N43RF
DATA STATION LOG**

MISSION NAME Amp # 3

FLIGHT ID 950113I

OPERATOR/S Riles, McNamara, BARR

TAPE ON SL 1357Z
 TAPE OFF SL 1628
 PRINTER ON 1256Z
 PRINTER OFF 1628
 FAST ON 1352
 FAST OFF 1628
 TAKE OFF 1355Z

CPU SELECTED (A) B
 CAMERAS USED N L R D
 CAMERAS ON NY
 CAMERAS OFF NY
 CAMERA COUNT NY
 LANDING 1626

ASDL MESSAGES

MSG	TIME	MSG	TIME	MSG	TIME	MSG	TIME
R V S B		R V S B		R V S B		R V S B	
R V S B		R V S B		R V S B		R V S B	
R V S B		R V S B		R V S B		R V S B	
R V S B		R V S B		R V S B		R V S B	
R V S B		R V S B		R V S B		R V S B	
R V S B		R V S B		R V S B		R V S B	
R V S B		R V S B		R V S B		R V S B	
R V S B		R V S B		R V S B		R V S B	
R V S B		R V S B		R V S B		R V S B	
R V S B		R V S B		R V S B		R V S B	
R V S B		R V S B		R V S B		R V S B	
R V S B		R V S B		R V S B		R V S B	

Mark out R-recco, V-vortex, S-sonde or B-AXBT to indicate type of ASDL message sent and annotate the time. Maintain Data Station Operator notes on the reverse of this page.

DATA STATION OPERATOR NOTES

1259Z Power glitch CPU-A and Terminal on UPS

No Noticeable effect, Rawtek went out and

LU 10 Screen went blank.

Brought LU 10 up by striking break

got to cm prompt. OFF'd cm to CI

7-12ed Hal PED got that back up.

RE-RAN Setup Just to be sure

everything was synced

1308Z FAST and Slow Tapes appear to be writing

as indicated by the Magical Amber led.

1321Z Power glitch on 1st engine shut down

LU 10 Blank/amber down CPU/HP term seem to be O.K.

RE-RAN Setup. Tapedecks appear to be running/writing

1344Z Engine start

1357Z IAU SP error, status 0226 Data overrun.