

Flt ID: H010613	From: KMCF	To: KMCF
Flt No.: 01-23	Blk In: 1616Z	ATA: 1606Z
ETD: 1430Z	Blk Out: 1430Z	ATD: 1443Z
ETE:	Blk Time: 1:46 (1.8)	Flt Time: 1:23 (1.4)
Sponsor Org: AOC	Program: HURR	Purpose: CHECK OUT FLT FOR N42RF

AOC Personnel

AC: KENUL	Sys Eng: ROLES
CP: HALVERSON	Data Sys: McMILLAN
Nav: ADLER	Radar:
FE: TORREY	GPS/BT: SMITH
Avionics:	Cld Phys:
FD: DAMIANO	

Participating Scientists/Visitors/AOC

Name (Last, First)	Activity on Aircraft	Affiliation
POSTON	OBS	AOC, CHIEF FLT BRANCH
MICKLE, TED	OBS	MACDILL AFB, FLT. MED.
SHEPHERD	OBS	AOC

Proposed/Actual Mission/Remarks (Recco, Fixes, Storm, PENET, NHOP #)

1355Z 24 30.02 T/O delayed due to RAMS problems.

(152022Z) Sonde splash pressure

1017.62 mb

Jeff ~~data~~ had a +.7 mb offset to ANAPS

12/64

U.S. Dept. of Commerce/NOAA/Aircraft Operations Center

AOCWF2

Flt ID: H010613

Time Off: 1443Z

Time On: 1606Z

A/C (Take Off)

Wx Stn (Take Off)

A/C (Land)

Wx Stn (Land)

Pressure

1016.2

1016.7

1016.4

1016.9

Number

Data Disposition/Date/Quality

Slow/Fast Flt Lvl Tapes

Radar Tapes

Cloud Physics Tapes

Video Tapes

AXBT

AXCP

AXCTD

Dropsondes

1

Video

Forward

Left Side

Right Side

Down

Remarks

Time On

Time Off

Rate

Remarks

IN 30 24

NO RA159

150320 JW not balancing
RA159 back (replaced)
went bad immedi

Flight ID: H010613

Page 7 of

U.S. Dept. of Commerce/NOAA/Aircraft Operations Center


Form 413-50

[illegible]

443x

N42RF Checkout Flight

010613Hs_P, 14:43:00-16:07:00



	mean	sigma	min	max
— s_latg_orig (deg), 1 s/sec	27.95	0.31	27.46	28.68
— s_longg_orig (deg), 1 s/sec	-83.60	0.77	-84.69	-82.37