

Flt ID: 020319N	From: PHNL	To: KRNO
Flt No.: 02-39	Blk In: 0230Z	ATA: 0225Z
ETD: 2100Z	Blk Out: 2042Z	ATD: 2053Z
ETE:	Blk Time: 5:48 (5.8)	Flt Time: 5:32 (5.5)
Sponsor Org: NCEP	Program: WINTER STORMS	Purpose: FLT# 19 TRANSIT TO MISSION ENROUTE RENO, NV

AOC Personnel

AC: McCANN	Sys Eng: GOLDSTEIN
CP: YATES/FINKE	Data Sys: CARPENTER
Nav:	Radar:
FE: KITSON	GPS/BT: SANS SOUL
Avionics:	Cld Phys:
FD: DAMIANO	CZYXK PM

Participating Personnel/USMS/NOAA/AOC

Name (Last, First)	Activity on Aircraft	Affiliation

Proposed/Actual Mission/Remarks (Recco, Fixes, Storm, PENET, NHOP #)

34
32

66
28

01562

62,6

17
-8

U.S. Dept. of Commerce/NOAA/Aircraft Operations Center					
Flt ID:		Time Off:		Time On:	
020319N		2053Z		0225Z	
		A/C (Take Off)	Wx Stn (Take Off)	A/C (Land)	Wx Stn (Land)
Pressure		1020.7	30.15	869.6	30.17
		Number	Data Disposition/Date/Quality		
Slow/Fast Flt Lvl Tapes		/			
Radar Tapes					
Cloud Physics Tapes					
Video Tapes					
AXBT					
AXCP					
AXCTD					
Dropsondes		10	All good; 10 messages sent		
Video					
	Forward	Left Side	Right Side	Down	Remarks
Time On					
Time Off					
Rate					
Remarks					

N49RF AVAPS DropSonde Log

N49RF Project: Winter Storms 2002 Flight ID 020319N

Mission: HNL → Reno Flight #: 19 System Status: OK

Drop #	Sonde Serial Number	Chn. #	Time (Zulu)	Press. offset	Winds time	Operator Initials	Comments / Drop Status / Failure Reason	GOOD ☒
1	003 135 315	1	2226	.3	23	DWC		✓
2	003 248 043	1	2244	.4	15	↓		✓
3	003 415 009	1	2303	0	33	↓		✓
4	003 135 312	1	2322	0	13	↓		✓
5	003 338 099	1	2341	.7	24	DSS		✓
6	003 135 314	1	0001	0	19	↓		✓
7	003 135 318	1	0020	0	10	↓		✓
8	003 338 112	1	0041	.6	22	ASG		✓
9	003 248 116	1	0104	.3	21	↓		✓
10	003 135 313	1	0128	.4	23	↓		
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								
31								
32								
33								

Flight ID 020319N

DAMIANO

Page 2 of 2

Storm TRANSIT

Drop #	Station ID	Time (UTC)	Lat (°N)	Lon (°W)	Sfc Prs mb	WX Cond.	Comments	OB #	SatComm Failures	Sent Time
1	003135315	222634	3140	15803	1020.4	BKN SCT SC	234602	1	1	2352
2	003248043	224450	3140	14803	1016.7	BKN AC	230319	2	—	2308
3	003476809	230819	3220	14556	1012.7	BKN SCT AC	232122	3	—	2326
4	003135312	232214	3500	14341	1009.0	BKN ccl AC	234247	4	—	2348
5	0032009	234139	3640	14146	1005.9	BKN CG	000032	5	—	0005
6	003135314	000103	3820	13843	1006.6	BKN-OVC CIR	002030	6	—	0025
7	003135318	002047	4000	13600	1009.2	OVC CIR	003504	7	—	0040
8	003338112	004150	4140	13301	1016.1	OVC CIR	005705	8	—	0102
9	003248016	010417	4220	12943	1019.3	OVC CIR	011940	9	—	0124
10	003135313	012816	4456	12558	1021.9	OVC SCT THN CIR	014558	10	—	0151

NO 108 KTS

4456
12558

March 19, 2002

NOAA49 Winter Storms Reconnaissance Modified Track 36 CC (Counter Clockwise)


PHNL 21 19.0N 157 55.6W
ZIGIE 24 18.8N 157 17.1W

	25 30N	155 00W	Turn 1	1018
Drop 1	30 00N	150 03W	First Drop	1019
Drop 2	31 40N	148 03W		1015
Drop 3	33 20N	145 56W		1014
Drop 4	35 00N	143 44W		1008
Drop 5	36 40N	141 16W		1006
	37 20N	140 00W	Turn 2	
Drop 6	38 20N	138 43W		1006
Drop 7	40 00N	136 00W		1008
Drop 8	41 40N	133 01W		1014
Drop 9	43 20N	129 43W		1020
Drop 10	45 00N	126 00W	Turn 3, Last Drop	1021

KRNO

39 30

119 46



NOAA/AOC/SED N49RF Flight Performance log

N49RF Project: US2002 Project No. 201 Flight No. RF19 Flight ID: 020319N
 SED Crew: ASG, CARPENTER, SANSsouci Mission: PHNL-KRNO
 Pre-Flight: 1950 Z Take-Off: 2053 Z Landing: 0225 Z

SYSTEM			Pre-Flight Check	In-Flight	Post-Flight Check	
N A V	IRS #1		<u>all</u>			
	IRS #2		<u>↓</u>			
	GPS Honeywell #1					
	GPS Honeywell #2					
	GPS Collins		<u>↓</u>		Off? ☒	
Nose Radar - Collins		<u>all</u>			Off? ☒	
T E M P / D P	Time	Temp °C			Time	Temp °C
	Temp #1	<u>2021</u>	<u>22.4</u>	<u>all</u>	<u>0228</u>	<u>14.6</u>
	Temp #2		<u>22.8</u>	<u>↓</u>		<u>16.3</u>
	Temp #3		<u>22.6</u>			<u>15.8</u>
	Temp #4		<u>22.6</u>			<u>16.8</u>
	DP Left		<u>11.6</u>		Cal. Time:	<u>-7.8</u>
	DP Right		<u>11.9</u>	<u>↓</u>	Cal. Time:	<u>-9.9</u>
CRYO			<u>N</u>		<u>NF</u>	
P R E S S	Attack Angle (ADCAOA)		<u>all</u>		<u>all</u>	
	Angle of Attack (APx, DAPx)		<u>↓</u>		<u>↓</u>	
	Sideslip (BPx, DBPx)					
	Static Pressure (PS1M, PS2M)					
	Dynamic Pressure (QCxM)		<u>↓</u>		<u>↓</u>	
	Radome Press. Lines		Checked? ☒ Date: <u>1/25/02</u>			
S Y S T E M S	SATCOM (Flight Phone) ☒		<u>DWC</u>		Off CB? ☒	
	Call COMSAT? ☒ (*292#)		CB's Checked? ☒ <u>DWC</u>			
	Iridium Phone		ON? ☒ <u>DWC</u>		OFF? ☒	
	FCU/UPS/CB		<u>all</u>		UPS off? ☐	
	MADS (WINDS/DISCWIN)		<u>all</u>		# DATs: <u>1</u>	
	Printer 1 (lp1)		Power? ☒ Paper? ☒		Printer Power off? ☐	
	MADS Cal. Date:		QC time: <u>2037</u>		QC time: <u>0226</u>	
	HAPS System		Time set? ☐ <u>Nu</u>		# Msg.: # Fail:	
	AVAPS System		<u>DWC</u>			
M I S C	Exterior Walk Around ☒		<u>DWC</u>			
	Inspect Drop Sonde Chute Bolts		<u>DWC</u>			
	Down Port Door (Ozone Inst.)		Cover OFF? ☒ <u>DWC</u>		Cover ON? ☒ <u>DWC</u>	
	AVAPS Sondes		# On Board: <u>24</u>	# Dropped: <u>10</u>	# Good: <u>10</u>	
	Sci. Power Monitor		<u>all</u>			
	APN-232 Altimeter		<u>all</u>			
	Modem		Power On? ☒ <u>DWC</u>			
	Additional Instrumentation:		L1 60Hz IP CB ON? ☒	After Take Off	L1 60Hz IP CB OFF? ☒	
	AL Ozone Data System		L1 400Hz CB ON? ☒	L1 Pump Switch ON? ☒	L1 400Hz CB OFF? ☒	
			Computer ON? ☒		Computer OFF? ☒	
Crew Responsibilities Assigned		<u>✓</u>				

1	DAT Tape #1	On: <u>2037</u>	Type: <u>VERB 60M</u>	Off: <u>0231</u>
	Comments:			