

N49RF AVAPS DropSonde Log

Project: WS '06 Flight ID: 060225n Flt Dir: Mayeaux
 Mission: _____ Flight #: RF14 Status: Sys 1 ☒ Sys 2 ☒ Launcher S/N: 02

Drop #	Sonde Serial Number	Chn. #	Time (Zulu)	Press. offset	Winds time	Operator Initials	Comments /Status/ Failure Reason	\$	GOOD ☒
1	053 316 051	1	2225	Ø	Ø	DWC	OK	N	✓
2	053 416 069	1	2244	Ø	Ø				✓
3	053 166 266	1	2305	Ø	2				✓
4	053 416 158	1	2329	Ø	1				✓
5	053 166 264	1	2353	Ø	3				✓
6	053 116 172	1	0018	Ø	Ø				✓
7	053 416 121	1	0039	Ø	2				✓
8	053 116 248	1	0101	Ø	1				✓
9	053 116 166	1	0122	Ø	1				✓
10	053 116 171	1	0144	Ø	3				✓
11	053 166 267	1	0208	Ø	3		Winds wrong early /ok later		✓
12	053 116 169	3	0210	Ø	2		Drop #11 b/u / same as Above		✓
13	053 416 157	4	0214	Ø	3		Drop #11 2nd b/u - OK		✓
14	053 416 149	1	0232	Ø	3		OK		✓
15	053 116 250	1	0256	Ø	1				✓
16	053 116 017	1	0322	Ø	2				✓
17									
18									
19									
20									
21									
22									
23									
24									
25									
26									
27									
28									
29									
30									
31									
32									
33									

\$ Codes A = AOC N = NHC/NWS H = HRD OW = NESDIS _____ = _____ = _____