

N49RF AVAPS DropSonde Log

Project: W.S. 06 Flight ID: 060306N Flt Dir: MARTY

Mission: TRK 8 Flight #: RF21 Status: Sys 1 OK Sys 2 OK Launcher S/N: 002

Drop #	Sonde Serial Number	Chn. #	Time (Zulu)	Press. offset	Winds time	Operator Initials	Comments /Status/ Failure Reason	\$	GOOD ☒
1	053416074	1	2013	0	05	WRB	REUF		☒
2	053166184	3	2035	.4	05				☒
3	053116071	4	2057	.5	04				☒
4	053170044	1	2122	0	06		NO GEOPNL ALT COLLINS OUT		☒
5	053170042	3	2142	0	08		NO GEOPNL ALT COLLINS OUT		☒
6	053170045	4	2205	0	06				☒
7	053166228	1	2227	.6	04				☒
8	053416089	3	2253	.6	03				☒
9	051926172	4	2319	.6	04				☒
10	053416152	1	2344	.4	05				☒
11	053416352	3	0001	0	06				☒
12	053416090	4	0019	.4	05				☒
13	053416224	1	0037	0	04				☒
14	053116177	3	0056	.5	05				☒
15	053416250	4	0115	0	04				☒
16	053416153	1	0133	0	04	✓	✓		☒
17									
18									
19									
20									
21									
22									
23									
24									
25									
26									
27									
28									
29									
30									
31									
32									
33									

\$ Codes A = AOC N = NHC/NWS H = HRD OW = NESDIS ____ = ____ = ____