

N49RF AVAPS DropSonde Log

Project: W/S 06 Flight ID: 060308N Flt Dir: MARTY

Mission: AIRONEMY Flight #: RF 23 Status: Sys 1 ☒ Sys 2 ☒ Launcher S/N: 002

Drop #	Sonde Serial Number	Chn. #	Time (Zulu)	Press. offset	Winds time	Operator Initials	Comments /Status/ Failure Reason	\$	GOOD ☒
1	053626 305	1	2212	.7	30	WFO	REF'S		☒
2	053626 307	3	2241	.5	06	↓	FAST FALL		☒
3	053626 303	4	2243	.4	24	↓	↓		☒
4	053636 119	1	2329	.7	08	↓	↓		☒
5									☒
6									
7									
8									
9									
10									
11									
12									
13									
14									
15									
16									
17									
18									
19									
20									
21									
22									
23									
24									
25									
26									
27									
28									
29									
30									
31									
32									
33									

\$ Codes A = AOC N = NHC/NWS H = HRD OW = NESDIS _____ = _____ = _____