

N49RF AVAPS DropSonde Log

Project: WS 06 Flight ID: 060315 Flt Dir: MARTY
 Mission: OZONE/NEP Flight #: RF25 Status: Sys 1 ☒ Sys 2 ☒ Launcher S/N: 002

Drop #	Sonde Serial Number	Chn. #	Time (Zulu)	Press. offset	Winds time	Operator Initials	Comments /Status/ Failure Reason	\$	GOOD ☒
1	053626252	1	00:02	+1.6	1	MER		N	☒
2	053626306	1	00:25	+1.6				N	☒
3	053636112	1	00:40	+1.6				N	☒
4	053416223		01:05	0				N	☒
5									
6									
7									
8									
9									
10									
11									
12									
13									
14									
15									
16									
17									
18									
19									
20									
21									
22									
23									
24									
25									
26									
27									
28									
29									
30									
31									
32									
33									

\$ Codes A = AOC N = NHC/NWS H = HRD OW = NESDIS _____ = _____ = _____